Report Date: <u>7/25/01</u>	Calendar Quarter: Second - 2001; April, May, June
Safety Recall Quarterly Report from 4/	26/01 through <u>6/30/01</u>
Manufacturer: Advanced Engine Manu	gement a.k.a. A.E.M.
Report Author: Kirk Miller	Phone: (310) 484-2322 ext. 237
Recall Subject: Air bypass valve / air by	pass valve retaining clip
1. NHTSA Safety Recall Campaign Nu	mber: <u>01E-018</u>
Also, for completeness, if your components your code: <u>N/A</u>	any has assigned a code number to this campaign, please
2. (a) The date notification to purchase	rs began: <u>April 26, 2001</u>
(b) The date notification of porchase	rs was completed: May 20, 2001
The total number of items involved in the subject distributors, and similar entities beyond the imme Number of Items Returned from Inv Includes (a) the total number of items returned from remedied prior to sale to consumers.	
Total number of items which were inspected and/ (b) Total Number Inspected & NOT Total number of items involved in the recall and it	REQUIRING REMEDY: 0 napocted, but determined to NOT REQUIRE REMEDIAL or recall repair work.
5. Items Determined to be Unreachable	•
Total Number Exported:	<u>0</u>
Total Number Stolen:	0
Total Number Scrapped:	0
Total Number Unable to Notify:	9- notice/return to sender
Total Number Otherwise Unreachable:	1-
Describe Other: Left incorrect phone nu	mber on voice mail/phone number disconnected.

^{&#}x27;Any questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Report Date: _10/22/01	Calendar Quarter: Third - 2001; Jul., Aug., Sept.
Safety Recall Quarterly Report from 7/01/01	through <u>9/30/01</u>
Manufacturer: Advanced Engine Manageme	ent g.k.a. A.E.M.
Report Author: Kirk Miller	Phone: (310) 484-2322 ext. 237
Recall Subject: Air bypass valve / pir bypass	valve retaining clip
1. NHTSA Safety Recall Campaign Number	r: <u>01E-018</u>
Also, for completeness, if your company ! provide your code: <u>N/A</u>	has assigned a code number to this campaign, please
2. (a) The date notification to purchasers be	egan: April 26, 2001
(b) The date notification of purchasers w	as completed: May 20, 2001
3. The Total Number of Items of Equipmen The total number of items involved in the subject came distributors, and similar entitles beyond the immediate	peign (including all items sold or distributed to purchasers, dealers,
Number of Items Returned from Inventor includes (a) the total number of items returned from M remedled prior to sale to consumers.	ory or Remedied Prior to Sale: 0 [anufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise
4. (a) Total Number Inspected & Remedied clips sent out via UPS. US mail Total number of items which were inspected and/or of	l: 164 air bypass valves; 4,861 air bypass valve retaining
(b) Total Number Inspected & NOT RE	
Total number of items involved in the recall and inspe	cted, but determined to NOT REQUIRE REMEDIAL or recall repair work.
5. Items Determined to be Unreachable	
Total Number Exported: 0	
Total Number Stolen:	
Total Number Scrapped: 0	
Total Number Unable to Notify: 9-	notice/return to sender
Total Number Otherwise Unreachable: 1-	<u> </u>
Describe Other: Left incorrect phone numb	er on voice mail/phone number disconnected.

^{&#}x27;Any questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Report Date: 4/23/02	Calendar Quarter: <u>First - 2002</u>
Safety Recall Quarterly Report from 1/0	01/02 through 3/31/02
Manufacturer: Advanced Engine Manag	rement a.k.a. A.E.M.
Report Author: Kirk Miller	Phone: (310) 484-2322 ext. 237
Recall Subject: Air bypass valve / air by	pass valve retaining clip
1. NHTSA Safety Recall Campaign Nu	mber: <u>01F-018</u>
Also, for completeness, if your compa provide your code: <u>N/A</u>	my has assigned a code number to this campaign, please
2. (a) The date notification to purchase	rs began: <u>April 26, 2001</u>
(b) The date notification of purchase	rs was completed: May 20, 2001
	ment Involved: 3.102 air bypass valves campaign (including all items sold or distributed to purchasers, dealers,
distributors, and similar entities beyond the imme	diste control of the manufacturer/importer).
Number of Items Returned from Inve Includes (a) the total number of items returned fro remedied prior to sale to consumers.	entory or Remedied Prior to Sale: 0 em Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise
clips sent out via UPS, US mail	died: 272 gir bypase valves; 4.910 gir bypass valve retaining
Total number of items which were inspected and/	•
(b) Total Number Inspected & NOT I Total number of items involved in the recall and it	REQUIRING REMEDY: 0
5. Items Determined to be Unreachable	
Total Number Exported:	0
Total Number Stolen:	<u>o</u>
Total Number Scrapped:	0
Total Number Unable to Notify:	9- notice of "return to sender" received
Total Number Otherwise Unreachable:	<u>1-</u>
Describe Other: Left incorrect phone nu	mber on voicemail:phone disconnected/not in service

¹Any questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Safety Recall Quarterly Report from 7/1/02 through 9/30/02 Manufacturer: Advanced Engine Management a.k.s. A.E.M. Report Author: Kirk Miller Phone: (310) 484-2322 ext. 237 Recall Subject: Air bypass valve / air bypass valve retaining clip 1. NHTSA Safety Recall Campaign Number: 01E-018 Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: N/A
Report Author: Kirk Miller Phone: (310) 484-2322 ext. 237 Recall Subject: Air bypass valve / air bypass valve retaining clip 1. NHTSA Safety Recall Campaign Number: 01E-018 Also, for completeness, if your company has assigned a code number to this campaign, please provide your
Recall Subject: Air bypass valve / air bypass valve retaining clip 1. NHTSA Safety Recall Campaign Number: 01E-018 Also, for completeness, if your company has assigned a code number to this campaign, please provide your
NHTSA Safety Recall Campaign Number: 01E-018 Also, for completeness, if your company has assigned a code number to this campaign, please provide your
Also, for completeness, if your company has assigned a code number to this campaign, please provide you
2. (a) The date notification to purchasers began: April 26, 2001
(b) The date notification of purchasers was completed: May 20, 2001
 The Total Number of Items of Equipment Involved: 3.102 air bypass valves The total number of items involved in the subject eampsign (including all items sold or distributed to purchases, dealers, distributors, and similar entities beyond the immediate control of the manufacture/importer).
Number of Items Returned from Inventory or Remedied Prior to Sale: 0 includes (a) the total autober of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to make to communers.
 (a) Total Number Inspected & Remedied: 410 air bypass valves; 4,921 air bypass valve retaining clips sen out via UPS, US mail. Total number of stems which were inspected and/or otherwise repaired or remedied.
(b) Total Number Inspected & NOT REQUIRING REMEDY: 0 Total number of Hense Involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
5. Items Determined to be Unreachable
Total Number Exported: 0
Total Number Stelea: 0
Tetal Number Scrapped: 0
Total Number Unable to Notify: 9- petice of "return to sender" received
Total Number Otherwise Unreachable: 1-
Describe Other: Left incorrect phone number on voicemail; phone disconnected/net in service

^{&#}x27;Any questions please contact Mrs. Kelly Schuler or Mr. Ion White at (202) 366-5227 or by FAX at (202) 366-7882.